Approved For Release 2002/06/17: CIA-RDP78B04747A001500030012-0

NPIC/TDS/D-1091-67 24 October 1967

	MEMORANDUM FOR THE RECORD	
25X1A	SUBJECT: Chip Comparator Progress Report	
25X1A	1. During the period 2-4 August personnel installed a temporary field modification to the 405 AM chip comparator to keep it in an operational status until such time as it can be sent to the factory for permanent modifications. On the 17th, 18th, and 23rd of August the technician returned to make minor adjustments to the machine. Since the 23rd of August, no maintenance adjustments of any sort have been made to the instrument except for water replenishment.	25X1A
	2. TDS will observe the operational reliability of the comparators without making any maintenance adjustments until the reliability drops below acceptable limits in order to determine mean time between failure. As soon as sufficient data is available, a routine preventative maintenance schedule will be set up to keep all of the comparators in peak operating condition.	th.
● 25X1A	3. At present, two 405B comparators are at	25X1A
25X1A	4. Based on the performance record of the 405AM for the past two months, indications are that the fundamental operational reliability problems with the chip comparators have been resolved, but that additional funding will be required. A cost analysis and work statement has been received from and is being forwarded to the respective components under separate memo for action.	
. DE(CLASS REVIEW by NIMA/DOD	

Approved For Redaise 2002/06/17 ACIA RDP78804747A001500030012-0

Approved For Release 2002/06/17 GIA-RDP78B04747A001500030012-0

- 5. An additional consideration concerning the operational use of the chip comparators, not previously covered, is the availability of computer time and software. Since four out of the six chip comparators are exclusively on-line, the operational availability of the chip comparators must therefore take into consideration the data processing as an essential element of consideration. It is my understanding from talking to IAS, TDS, and DIA personnel that that the data processing problem is of extreme concern to them. Also affecting the operational acceptability of the chip comparators are the building facility requirements and training programs. Since the chip comparators are highly sophisticated pieces of equipment, they impose special building facility and training requirements on the Center.
- 6. In summary, TDS feels that the solution for the basic reliability and maintainability of the chip comparators has been resolved from the technical viewpoint, but that the operational acceptability is dependent upon additional considerations beyond its control; namely, the required additional funding, the data processing capability, training, and building facility maintenance.

25X1A

Distribution:

Original - Route & File

1 - O/Dir (Technical Advisor)

1 - O/Dir (Special Assistant)

1 - NPIC/PAG

1 - NPIC/IAS

1 -- NPIC/TID

1 - DIA (Attn:

1 - NPIC/TDS/EPS

1 - NPIC/TDS/DS

1 - NPIC/TDS

5X1A

Approved For Release 2002/06/			5	24 Oct 67
то		INITIALS	DATE	REMARKS
DIR				
DEP/DIR				
EXEC/DIR				
TECH ADV				
SPECIAL ASST				
CH/SS				
AS OR P&M				
ASST FOR OPS				
ASST FOR PA				
ASST FOR TO	Χ	-	2	In view of the interest con- cerning the operational status
CH/CSD			1	of the chip comparators, the attached memo for the record
CH/IPD			1	is being forwarded to keep you
CH/PD				up to date in this matter.
CH (ASD				3.77.11.1
-CH7-TID				
CH/IAS/DDI				
CH/DIA/XX-4				
CH/DIA/AP-IP				_
CH/SPAD				
LO/CGS/CIA				_]